

ਵੱਲੋਂ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ
ਪੈਰਾਮਾਊਂਟ ਪਬਲਿਕ ਸਕੂਲ
ਚੀਮਾਂ (ਜਿਲ੍ਹਾ ਸੰਗਰੂਰ)।

ਨੰਬਰ 631 ਮਿਤੀ 26.4.2022

ਵਿਸ਼ਾ: ਸਾਲ 2022-23 ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ: ਆਪ ਜੀ ਦਾ ਪੱਤਰ ਨੰ: PPS/0563/April-2022 ਮਿਤੀ 25-04-2022

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਰਾਹੀਂ ਪ੍ਰਾਪਤ ਹੋਇਆ ਕੇਸ ਲੋੜੀਂਦੀ
ਇੰਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਸਮੇਤ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ
ਜਾਂਦਾ ਹੈ ਜੀ। ਲੋੜੀਂਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਬਾਬਤ ਰੁਪਏ 5000/- ਜੀ.ਆਰ ਨੰ: 663699 ਮਿਤੀ 26.4.2022

ਰਾਂਹੀ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।

ਨੱਥੀ / ਸਰਟੀਫਿਕੇਟ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਮਿਤੀ

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ
ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ ਜੀ ਨੂੰ ਸੂਚਨਾਂ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।


Part-II

Building Safety Report

Name of School: Paramount Public School, Cheema, (District Sangrur).

I have visited the above-mentioned School Building along with Sh. Gurpreet Singh Dhillon / A.E. and on visually inspection; it seems visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings Sft.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to **One Year, upto 31/03/2023**


Sub Divisional Engineer
Provincial Sub Division PWD, B&R
Sangrur.