

## BUILDING SAFETY CERTIFICATE

No. 41

Dated 28/04/2025

It is certified that the existing building **PARAMOUNT PUBLIC SCHOOL**, at **Village- Cheema, Sunam Bathinda Road, Tehsil- Sunam Distt.- Sangrur, Punjab -148029** is having block(s)/Floor(s) as per details below:

Detail of Block (s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor (s) in the Block	3	3	3	--	--	--

The building is owned/occupied by building **PARAMOUNT PUBLIC SCHOOL, CHEEMA** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers <sup>Sh. Shubham Goyal, JE</sup> concerned of **PWD B & R, Sangrur, Punjab** on 25/04/2025 in the presence of **Mr Jasvir Singh, Chairman Paramount Charitable Society, Village Cheema, Tehsil- Sunam. Sangrur -148029** and that the building/premises is fit for occupancy for running school with effect from **01.04.2025** to **31.03.2026** for a period of **ONE** years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1) In case of any addition, alteration or expansions and modification to this building are done; certificate may be re-obtained after completion of undersigned.
- 2) In case the building is affected by flood or if there is settlement of walls/foundation or sagging of roofs etc, immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- 3) A separate certificate regarding Fire Fighting & Fire Safety Guidelines should be obtained from the competent authority.
- 4) A separate certificate regard Electrical Works should be obtained from the competent authority.
- 5) The owner of the building/ Management is fully responsible regarding safety of building from all angles in spite of this report.

  
Sub Divisional Engineer  
Cons. Sub Division No. 2  
P.W.D. B&R SANGRUR.

Continue page 2...

(2)

- 6) The coverage area of the building is 65596 Sq.ft.
- 7) This Report is not valid for legal purpose.
- 8) This building visually seems safe to occupy for the normal use up to: 31/03/2026
- 9) This Building Certificate should not be considered as NOC for Road Access which will be taken separately by the School as per Government Policy No. 5/13/2018-3BR3/1294287/3 Dated: 10.08.2018
- 10) Building Safety Certificate Fees paid vide GR No. 675357 Dated: 28/04/2025

Issued on 28/04/2025 at PWD B & R, Sangrur, Punjab by SDE, Const. Sub Div. No. 2 PWD B & R Sangrur.

Signature with Seal : \_\_\_\_\_

Name : \_\_\_\_\_

Designation : Sub Divisional Engineer  
Const. Sub Division No. 2  
PWD- B&R SANGRUR.

Name & Address of Department/ Office

## Part-II

### Building Safety Report


Name of School: PARAMOUNT PUBLIC SCHOOL (SANGRUR)

Sh. SHUBHAM GOYAL (Junior Engineer) has visited the above mentioned school on dated 25/04/2025 and on his visual inspection; the building seems to be safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings. Bearing capacity, Foundation detail, Structural Drawings. Technical Specifications. Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) This Certificate holds validity with valid Fire Safety Safety Certificate. A separate certificate regarding Fire Fighting should be obtained from the competent Authority
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings Stt.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to One Year, upto 31-03-2026

  
J.E  
(Shubham Goyal)

  
Sub Divisional Engineer  
Const. Sub Divn.No.2 PWD, B&R  
Sangrur.



(Provincial)

675357

28/04/2025

Serial No. Y

Received from

Principal Payment  
Public School

with letter No

dated

28/04/2025

the sum of Rupees

15,000

[Fifteen thousand only]

in Cash/by Cheque on account of

Building Safety

in payment of

Inspection fee

Rs

Signature

Sub Divisional Engineer  
Comp. Sub Division No. 2  
P.W.D. BAR SANGRUR

Date